IN THE DRAWINGS:

Enclosed with this response are three replacement drawing sheets. These replacement
drawing sheets replace originally filed drawing sheets 2, 3, and 4. The changes in these
replacement sheets address the Examiner's objections to the drawings. Specifically, in Figure 2,
the value associated with V2 is changed to 0.5325v. In Figure 4, the value associated with V2 is
also changed to 0.5325v and V1 is added next to the 1.25v input to differential receiver 402. In
Figure 6, reference numeral 618 is added to identify the inverter for signal B.

2

3

Appl. No. 09/640, 802 Arndt. Dated 05-15-2004 Reply to Office action of Feb. 23, 2004

2/5

Replacement Sheet




FIG. 2




FIG. 3

Appl. No. 09/640, 802 Amdt. Dated 05-15-2004 Reply to Office action of Feb. 23, 2004

3/5

Replacement Sheet





FIG. 4



Appl. No. 09/640, 802 Amdt. Dated 05-15-2004

Reply to Office action of Feb. 23, 2004

4/5

Replacement Sheet

p.22

